

May Cemetery Report

There have been 2 memorial permits issued

Receipts for April totalled £165

The dry stone walling repairs following storm Arwen have been completed by G W Bell

The faulty glazing and beading have been replaced in the large windows facing the car parking area, work undertaken at no cost to Council.

The tree surveyor Jon Oliver has carried out a visual inspection of the cemetery trees, no defects were identified. A full inspection to include a written report will take place in August this year when all the APC trees including the cemetery will be surveyed.

Could Council give approval for the Annual servicing and cleaning of the Chapel

Quotes :

Full clean of Chapel interior £180 no vat

Exterior and interior of Chapel windows including removal of cobwebs in the rafters £50 no vat

Servicing of Chapels fire extinguishers £59.05 plus vat

Servicing of intruder alarm and emergency lighting £70 plus vat

PAT testing electrical equipment £ quote imminent

Brenda Brockbank

Cemetery Officer